EAST Search History

Ref #	Hits	Search Query	D8s	Default Operator	Plurals	Time Stamp
L1	1086	(307/104,109).CCLS.	US-PGPUB; USPAT	OR	OFF	2007/03/16 09:06
L2	521390	(detect detecting detector detection sensing sensor measure measuring) near4 "3" voltage near2 phases	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/16 09:07
L3	15608	(detect detecting detector detection sensing sensor measure measuring) near4 voltage near2 phases	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/16 09:07
L4	2	1 and 3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/03/16 09:07
L5	181898	(detect detecting detector detection sensing sensor measure measuring) near4 phases	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/16 09:07
L6	10	1 and 5	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/16 09:07